



Safer, Stronger, Smarter Networks

Turbine Bearing Failure Case Study



www.eatechnology.com

Analytical Facilities

Oil Diagnostics Labs

Switchgear, Transformers & Tap Changers

- Moisture
- Acidity
- Breakdown Voltage
- Filtration
- DGA




Analytical Facilities

- Optical Microscopy
 - Low Powered Optical Microscope (64x)
 - High Powered Optical Microscope (1000x)
 - Image Analysis



Analytical Facilities

- Scanning Electron Microscopy (SEM)
 - TESCAN (1,000,000x)
 - Bruker Energy Dispersive X-ray Analysis (EDAX) – Elemental Analysis



Analytical Facilities

- Mechanical Testing
 - Tensile Testing Machine (5kN & 250kN)
 - Torsion Testing
 - Vickers Hardness
 - Surface Roughness Assessment



The asset

- Blade bearings
- In service for 10 years
- Protective coverings – off for unknown period
- 4-point contact ball bearing system
- Induction hardened raceway – leave a ‘soft’ spot
- Maintenance period – every 6 months
- Actual maintenance - unknown

The issue

- Multiple pitch errors across one site
- Vibration of the turbines
- Seizing of 2 of the blades on 1 turbine
- Possible more seizing across site




Dismantling & Inspection




- General external condition
- Gasket assessment & removal
- Water ingress assessment
- Filler plug removal
- Ball bearing removal & conditioning
- Sectioning
- Raceway and cage assessment
 - Outer and inner ring
- Grease assessment
 - General condition
 - Elemental analysis





Ball bearing condition






Sectioning



Cage running surface



Cage condition




Dismantling & Inspection

- Indentations – Material debris from cage/running surface
- Spawling of the raceway and raceway breakup




Raceway degradation

- Rolling contact fatigue
 - Material indentations
 - Lack of/poor lubrication
 - Sliding motion of ball bearings




Raceway degradation

- Low level vibration corrosion – False brinelling
 - Caused by micro movements under cyclic vibration
 - No significant wear or corrosion present



Grease assessment

- Reasonable condition
 - Dark, fluid, slightly thickened suggesting aging
 - Some but not significant levels of material debris
- Elemental analysis
 - Iron (Fe) present



Summary

- Good external and gasket condition
- Evidence of water ingress – rusting
 - Weather protection not in place
- Reasonable grease condition – small amounts of metal particulate
 - Suggests grease has been changes recently
- Cage and running edge wear – severe scoring and material loss
 - Caused by sliding friction and material debris – inadequate lubrication and radical clearance
- Severe raceway degradation & breakup
 - Indentation damage caused by material debris/inadequate lubrication
 - No significant degradation around ‘soft’ spot region 0 indicating failure was not due to the surface hardening or installation processes
 - Evidence of false brinelling – bearing vibration has occurred, could be secondary due to spawling and raceway breakup
- Route cause
 - Poor/inadequate lubrication or inadequate maintenance policy

Asset Management

- Implications

- Installation practices
- Maintenance practices
- Condition assessment
- Monitoring

- Considerations

- Maintenance – grease sample, metallic particulate analysis
- Permanent online monitoring
- Vibration detection
- Torque, lubrication quality & temperature detection
- Automatic grease systems



Thank you

For further information

Call +44 (0) 151 347 2313 or Email sales@eatechnology.com

www.eatechnology.com

Australia | China | Europe | Singapore | UAE | USA

Main reception: +44 (0) 151 339 4181
EA Technology, Capenhurst Technology Park,
Capenhurst, Chester, CH1 6ES, United Kingdom